



ALL BALLS
Better Bearings & Components

The Industry's Deepest,
Broadest Product Range.

www.GOallballs.com

TECHNICAL INNOVATION

DATE: 05/2007

APPLICATIONS:

ATV

CATEGORY:

Differential Bearing Kit

DESCRIPTION:

Honda Pinion Gear Repair Sleeve

All Balls Racing Products

822 North Reading Avenue P.O. Box 437
New Berlinville, PA 19545
Phone: (888) 228-3323 or (610) 473-0505
Fax: (888) 552-0557 or (610) 473-8411

Part No. 40-2194 is a repair sleeve for the needle bearing surface of the input shaft. A needle bearing failure in Honda differentials often causes damage to the input shaft. In those instances, the ring and pinion often need to be replaced. It is now possible to repair the worn input shaft bearing surface with our repair sleeve. The shaft must be machined to allow the repair sleeve to press fit onto the shaft. The machining operation should be handled by a competent machine shop only.