



L208008

29-06-23 REV.02



leovince.com




International Customer Service:  
info@leovince.com

North America Customer Service:  
infousa@leovince.com - +1-844-536-7625



# ART 208008R

## LAMBDA WIRE EXTENSION HARNESS





### FOR YAMAHA TÉNÉRÉ 700 EURO 5

TYPE: DM11; A/01, A/03, A/07, A/09, A/11 -  
DM15; A/01, A/03 - DM16; A/01, A/03


**FITMENT NOTICE FOR NON-EUROPEAN COUNTRIES:**


Wire extension harness is required only if your O2 sensor is near the exhaust ports on motor.



NOTE / NOTES / REMARQUES /  
ANMERKUNGEN / NOTAS

NOTE / NOTES / REMARQUES /  
ANMERKUNGEN / NOTAS





NOTE / NOTES / REMARQUES /  
ANMERKUNGEN / NOTAS