


SS 2400 SHIELD REMOVAL




STEP 1.

TO REMOVE THE CHIN BAR FROM THE SS2400 HELMET, PRESS THE RELEASE BUTTON LOCATED ON THE SIDE OF THE HELMET, PULL THE CHIN BAR FREE. REPEAT ON THE OTHER SIDE TO COMPLETELY REMOVE THE CHIN BAR.



STEP 2.

PULL THE VISOR DOWN JUST SLIGHTLY BELOW THE TOP OF THE HELMET, THEN GENTLY PULL EACH SIDE OF THE VISOR FREE FROM THE LOCKING MECHANISM.



STEP 3.

TO REINSTALL THE CHIN BAR, SIMPLY LINE UP THE ANCHORS TO THE SLOTS IN THE HELMET, AND PRESS INTO PLACE.