# **Arctic-Cat "2-HOLE" Winch Converter Mount**

### **Winch Mount**


#### PART # 100500

## **Kit Components:**

<u>Qty</u>	Part Description
1	Mount Bracket
4	5/16"-18 x 1" Hex Head Flange Bolts
4	5/16" SAE Flat Washers
4	5/16"-18 Locking Hex Nuts


# **INSTALLATION INSTRUCTIONS:**

- 1. Assemble the Mount to your winch with the hardware provided with your winch as shown in "Figure 1" (some winches will have the motor to the right and some to the left).
- 2. Install winch and mount assembly to the location shown in "Figure 2" using the supplied 5/16" hardware. (winch not shown for clarity)
- 3. Install your roller fairlead to OEM Frame Location. "Figure 3"
- 4. Recommended Contactor location shown in "Figure 4"
- 5. Using the instructions provided with your winch, wire accordingly.





Fairlead Location



"Figure 3" Fairlead location

Contactor Location

"Figure 4" Contactor Location

